

# SKF Technical Bulletin

## VKBA 6543 – Mandatory replacement of the protective rings



VOLVO C30, C70 II, S40 II, V50



**Mandatory replacement of the Protective rings during the wheel bearing fitting**



OE Nb: 31340604

In line with OE recommendations to replace the Protective rings during the wheel bearing mounting, SKF has added them in the Wheel bearing kit VKBA 6543 from Batch code 24 O. It is mandatory to replace the old ring as it can be damaged during the bearing removal or when fitting the new one.

**Note!** Depending on the driveshaft length, only one ring needs to be changed! Check the length of the Driveshaft of the vehicle before mounting the new bearing.



VKBA 6543



**YouTube** [Click here to watch SKF technical videos on Youtube!](#)

© SKF Group 2017

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use

