



Typ 1B



Typ 1C

www.vdo.com

TPMS application and use list - 10/2015

Vehicle make/ Model	from	to	Restrictions	OE number Sensor	Identification Sensor	Order number Aftermarket	Order number Service kit	Order number Valve stem	Generation	Torque Hex nut	Torque Valve core
BMW											
1-series (F20, F21)	03.2014			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
2-series (F22, F23, F45, F46)	03.2014			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
3-series (F30,F31,F34)	03.2014			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
4-series (F32, F33, F36)	03.2014			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
i3 (I01)	08.2013			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
i8 (I12)	03.2014			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
M3 (F80)	04.2014			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
M4 (F82, F83)	04.2014			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
X1 (F48)	07.2015			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
X5 (F15, F85)	05.2013			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
X6 (F16, F86)	08.2014			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
Citroen											
C4	11.2004	06.2008		5430T4	S120123004	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
C5	09.2004	09.2013		5430T4	S120123004	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
C6	09.2005	12.2012		5430T4	S120123004	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
C8	09.2005	06.2014		5430T4	S120123004	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
C4 Aircross	04.2014			1612477080	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8Nm	0,4Nm
Fiat											
2F Nuovo Ulysee	01.2001	10.2010		9673198500	S120123004	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
Ford *1)											
Galaxy (WA6)	05.2006	04.2015		8G92 1A189-KB	S180052020	S180084730Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
S-Max (WA6)	05.2006	04.2015		8G92 1A189-KB	S180052020	S180084730Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
Mondeo IV (BA7)	03.2007	12.2014		8G92 1A189-KB	S180052020	S180084730Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
Honda*3)											
Accord	07.2013			42753-TL0-G520	S180052059	S180052059Z	A2C59507829	A2C59517072	TG1C	8Nm	0,4Nm
Jazz	11.2014	12.2015		42753-TL0-G520	S180052059	S180052059Z	A2C59507829	A2C59517072	TG1C	8Nm	0,4Nm
Hyundai *2)											
Genesis	01.2014			52933 3N100	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Grand Santafe (NC)	05.2013			52933 3N100	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
i20 (PB)	08.2008	06.2014		52933 1J000	S180052012	S180084710Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
i20 MY 2012 (PB)	06.2014			52933 2M650	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
iX20 (JC)	11.2010	09.2013		52933 1J000	S180052012	S180084710Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
iX20 (JC)	05.2013			52933 3N100	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
i30 (FD)	10.2007	06.2012		52933 2L600	S180030002	S180014820Z	S180014531A	n.A.	TG1B	8Nm	0,4Nm
i30 (GD)	11.2011			52933 3N100	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Santa Fe (DM)	08.2012			52933 3N100	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Infiniti											
Q50	04.2013			407003JA0A	S180052036	S180052036Z	A2C59507830	A2C59517072	TG1C	8Nm	0,4Nm
Jaguar *1)											
F-Type (X152)	10.2012			C2D21599	S180052028	S180052028Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
F-Pace (X761)	12.2015			S180052076	S180052076Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm	
XE (X760)	02.2015	11.2015		C2D21599	S180052028	S180052028Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm

Vehicle make/ Model	from	to	Restrictions	OE number Sensor	Identification Sensor	Order number Aftermarket	Order number Service kit	Order number Valve stem	Generation	Torque Hex nut	Torque Valve core
Jaguar (cont'd)											
XE (X760)	12.2015				S180052076	S180052076Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
XF (X250)	03.2008			C2C41655	S180052080	S180052080Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
XF (X260)	06.2015				S180052076	S180052076Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
XJ (X350)	05.2003	09.2009		C2C41655	S180052080	S180052080Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
XJ (X351)	10.2009			C2D21599	S180052028	S180052028Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
XK (X150)	03.2006	07.2014		C2C41655	S180052080	S180052080Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
Kia											
Carens (RP)	12.2012			52933 3N100	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Cee'd	12.2006	08.2012		52933 2L600	S180030002	S180014820Z	S180014531A	n.A.	TG1B	8Nm	0,4Nm
Cee'd (JD)	03.2012			52933 3N100	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Optima Hybrid	03.2012	08.2013		52933 1J000	S180052012	S180084710Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Optima (TF)	08.2013	06.2015		52933 2M650	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Optima Hybrid (TFe)	03.2014	06.2015		52933 2M650	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Optima	08.2015			52933 D4100	S180052062	2910000102300	A2C59507828	A2C59517072	TG1C	8Nm	0,4Nm
Picanto (TA)	04.2014			52933 3N100	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Sorento	11.2009	09.2012		52933 1J000	S180052012	S180084710Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Sorento (XM, UM)	07.2012			52933 3N100	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Soul (AM)	02.2009	12.2013		52933 1J000	S180052012	S180084710Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Venga (YN)	02.2010	04.2014		52933 1J000	S180052012	S180084710Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Venga (YN)	04.2014			52933 3N100	S180052092	S180052092Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Lada											
Granta	04.2015			407003VU0A	S180052048	S180052048Z	A2C59506227	A2C59517072	TG1C	8Nm	0,4Nm
Lancia											
TC Phedra	01.2001	10.2010		9673198580	S120123004	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
Land Rover *1)											
Discovery 3 (B3)	07.2004	09.2009		LR032835	S120123002	A2C59511308	S180014561A	n.A.	TG1B	8Nm	0,4Nm
Discovery 4 (B4)	09.2009			LR066378	S180052028	S180052028Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
Discovery Sport	10.2014			LR066378	S180052028	S180052028Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
FreeLander	10.2006			LR058023	S180052028	S180052028Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
Range Rover (D4)	2005	2009		LR032835	S120123002	A2C59511308	S180014561A	n.A.	TG1B	8Nm	0,4Nm
Range Rover (D5, D6)	2010	05.2015		LR066378	S180052028	S180052028Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
Range Rover (D6)	06.2015				S180052076	S180052076Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
Range Rover Evoque (F1)	2012			LR066378	S180052028	S180052028Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
Range Rover Sport (E1)	2005	2009		LR032835	S120123002	A2C59511308	S180014561A	n.A.	TG1B	8Nm	0,4Nm
Range Rover Sport (E2, E3)	2010	05.2015		LR066378	S180052028	S180052028Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
Range Rover Sport (E3)	06.2015				S180052076	S180052076Z	S180084520A	A2C59517073	TG1C	8Nm	0,4Nm
Mazda *1)*3)											
2 (DE)	05.2014			BHB637140	S180052054	S180052054Z	A2C59507828	A2C59517073	TG1C	8Nm	0,4Nm
3 (BL)	06.2009	03.2013		BHB637140	S180052054	S180052054Z	A2C59507828	A2C59517073	TG1C	8Nm	0,4Nm
5 (CW)	09.2010			BHB637140	S180052054	S180052054Z	A2C59507828	A2C59517073	TG1C	8Nm	0,4Nm
6 (GH)	08.2007			BHB637140	S180052054	S180052054Z	A2C59507828	A2C59517073	TG1C	8Nm	0,4Nm
CX5 (KE)	11.2011			BHB637140	S180052054	S180052054Z	A2C59507828	A2C59517073	TG1C	8Nm	0,4Nm
CX7 (ER)	06.2009			BHB637140	S180052054	S180052054Z	A2C59507828	A2C59517073	TG1C	8Nm	0,4Nm
CX9 (TB)	08.2010			BHB637140	S180052054	S180052054Z	A2C59507828	A2C59517073	TG1C	8Nm	0,4Nm
Mercedes Benz											
CLS (C219)	01.2005	07.2009	ab A 006846	A 002 540 80 17	S122228002	S180014730Z	S180014541A	n.A.	MB	6Nm	0,4Nm
E-Class (W211)	03.2005	03.2009		A 002 540 80 17	S122228002	S180014730Z	S180014541A	n.A.	MB	6Nm	0,4Nm
GL-class (X164)	09.2006	07.2009	bis A 536007	A 002 540 80 17	S122228002	S180014730Z	S180014541A	n.A.	MB	6Nm	0,4Nm
M-Class (W164)	07.2005	07.2009	bis A 536007	A 002 540 80 17	S122228002	S180014730Z	S180014541A	n.A.	MB	6Nm	0,4Nm
R-Class (W251)	01.2006	07.2009	bis A 101972	A 002 540 80 17	S122228002	S180014730Z	S180014541A	n.A.	MB	6Nm	0,4Nm
S-Class (W221)	10.2005	06.2009	bis A 293047	A 002 540 80 17	S122228002	S180014730Z	S180014541A	n.A.	MB	6Nm	0,4Nm
S-Class Coupe (C216)	05.2006	06.2009	bis A 024016	A 002 540 80 17	S122228002	S180014730Z	S180014541A	n.A.	MB	6Nm	0,4Nm
SL (R230)	01.2005	07.2009	ab F 099797	A 002 540 80 17	S122228002	S180014730Z	S180014541A	n.A.	MB	6Nm	0,4Nm
Sprinter NVC 3 (906)	06.2006	06.2014		A 002 540 95 17	S122228004	A2C59511309	A2C59511332	n.A.	MB	6Nm	0,4Nm
Viano/Vito (W639)	06.2006	09.2014		A 002 540 95 17	S122228004	A2C59511309	A2C59511332	n.A.	MB	6Nm	0,4Nm
MINI											
Cooper (F55, F56)	3.2014			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
One (F55, F56)	3.2014			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
Clubman (F54)	07.2015			36 10 6 856 209	S180052056	S180052056Z	A2C59506228	A2C59517073	TG1C	8Nm	0,4Nm
Mitsubishi											
ASX (ZC)	08.2014			4250C477	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8Nm	0,4Nm
Lancer (GS41)	08.2014			4250C477	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8Nm	0,4Nm
L200 (CR)	08.2014			4250C477	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8Nm	0,4Nm
Outlander (RE)	07.2014			4250C477	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8Nm	0,4Nm
Pajero (BK)	07.2014		Felgen- kompatibilität prüfen!	4250C275	S180150004	S180052094Z	A2C59507087	A2C59517072	TG1C	8Nm	0,4Nm
Spacestar (EL)	07.2014			4250C275	S180150004	S180052094Z	A2C59507087	A2C59517072	TG1C	8Nm	0,4Nm



Vehicle make/ Model	from	to	Restrictions	OE number Sensor	Identification Sensor	Order number Aftermarket	Order number Service kit	Order number Valve stem	Generation	Torque Hex nut	Torque Valve core
Nissan											
Murrano (P42M)	10.2014			407003JA0A	S180052036	S180052036Z	A2C59507830	A2C59517072	TG1C	8Nm	0,4Nm
Note (J02C)	08.2013			407003VU0A	S180052048	S180052048Z	A2C59506227	A2C59517072	TG1C	8Nm	0,4Nm
NV200 EV (X12K)	04.2014			407003VU0A	S180052048	S180052048Z	A2C59506227	A2C59517072	TG1C	8Nm	0,4Nm
Pathfinder (P42K)	06.2013			407003JA0A	S180052036	S180052036Z	A2C59507830	A2C59517072	TG1C	8Nm	0,4Nm
Pulsar (B12L)	07.2014			407003VU0A	S180052048	S180052048Z	A2C59506227	A2C59517072	TG1C	8Nm	0,4Nm
Qashqai (P32S)	12.2013			407003VU0A	S180052048	S180052048Z	A2C59506227	A2C59517072	TG1C	8Nm	0,4Nm
X-Trail (P32R)	11.2013			407003VU0A	S180052048	S180052048Z	A2C59506227	A2C59517072	TG1C	8Nm	0,4Nm
Peugeot											
1007	04.2005	12.2009		5430T4	S120120001	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
207	02.2006	09.2013		5430T4	S120120001	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
307	11.2003	12.2006		5430T4	S120120001	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
407	05.2004	02.2006		5430T4	S120120001	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
508	11.2010	09.2013		5430T4	S120120001	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
607	10.2004	03.2009		5430T4	S120120001	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
807	10.2004	06.2014		5430T4	S120120001	S180014805Z	S180014561A	n.A.	TG1B	8Nm	0,4Nm
4008	11.2014			1612477080	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8Nm	0,4Nm
Renault											
Espace V *4)	06.2015			407004CB0A	S180150006	2910000063100	n.A.	2910000063400	TG1D	-	-
Fluence	02.2010			40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8Nm	0,4Nm
Kadjar	06.2015			407004CB0A	S180150006	2910000063100	n.A.	2910000063400	TG1D	-	-
Koleos	12.2013			407003VU0A	S180052048	S180052048Z	A2C59506227	A2C59517072	TG1C	8Nm	0,4Nm
Laguna III	10.2007			40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8Nm	0,4Nm
Latitude	02.2011			40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8Nm	0,4Nm
Megane II	11.2002	11.2008		40 70 055 78R	S120123006	S180014810Z	S180014500A	n.A.	TG1B	8Nm	0,4Nm
Megane III	11.2008			40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8Nm	0,4Nm
Scenic II	06.2003	07.2010		40 70 055 78R	S120123006	S180014810Z	S180014500A	n.A.	TG1B	8Nm	0,4Nm
Scenic III	02.2009			40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8Nm	0,4Nm
Spider	03.2010			40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8Nm	0,4Nm
Zoe	09.2012			40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8Nm	0,4Nm
Suzuki											
Jimny	11.2014			43139-61M00	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Swift	04.2014			43139-61M00	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
SX-4	06.2014			43139-61M00	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
SX-4 S-Cross	08.2013			43139-61M00	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Vitara	02.2015			43139-61M00	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8Nm	0,4Nm
Tesla											
Model S MY 2015	09.2014			1034602-00-A	S180052068	S180052068Z	A2C59507831	A2C59517072	TG1C	8Nm	0,4Nm
Volkswagen											
New Beetle	2006	07.2010		1K0 907 253 C	C122215002	S180014701Z	S180014511A	n.A.	TG1B	8Nm	0,4Nm
Passat / Passat Synchro	03.2005	11.2010		1K0 907 253 C	C122215002	S180014701Z	S180014511A	n.A.	TG1B	8Nm	0,4Nm
Crafter	04.2006	06.2014		2E0 907 508 F	S122228004	A2C59511309	A2C59511332	n.A.	MB	6Nm	0,4Nm
Volvo *1) *3)											
C30	10.2006			31302096	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
C30 Electric	12.2010			31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
C70	03.2006			31302096	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
S40	01.2004			31302096	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
S60	01.2011			31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
S80L	03.2006			31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
S80	03.2006			31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
V50	04.2004			31302096	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
V60	09.2010			31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
V70	03.2006			31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
XC60	05.2008			31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm
XC70	02.2007			31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8Nm	0,4Nm

¹⁾ If a service kit for a sensor of type TG1B is needed for the Ford, Jaguar, Land Rover, Mazda or Volvo brand, use article number S180014561A.

²⁾ If a service kit for a sensor of type TG1B is needed for the Hyundai brand, use article number S180014531A.

³⁾ These vehicle models are only be equipped with direct tire pressure monitoring systems as option.

⁴⁾ Max. designed speed of TG1D sensors: 200km/h. „Renault Espace V Models“ with the engine types dCi 160 EDC and TcE 200 EDC can use the TG1C sensor S180052048Z in specifically approved OEM and IAM rims as an alternative.

